



Safety brief



Thursday, August 10, 2017

Did you Know?

Product Recall – Genie SX-150 and SX-180 aerial lifts

Genie is recalling SX-150 and SX-180 wear pads. The affected aerial lifts were manufactured between 2014 and 2017.

Models and Serial Numbers Affected:

SX-150: SX15015H-101 to 161
 SX15016H-162 to 228
 SX150H-500 to 501

SX-180: SX18014-101 to 196
 SX18015-197 to 313
 SX18016-314 to 317
 SX18016H-318 to 360
 SX180H-600 to 602

Why is the product being recalled?

- Genie Industries has found that weld debris in the boom tubes could lead to premature and excessive wear of the upper wear pads. This excessive wear can lead to potential damage to the boom tubes and could cause the platform to drop.

What if I have found an affected lift?

- Using the table below, order the appropriate kit to replace the wear pads on your machine.

Model	Kit PN
SX-150	1280093GT
SX-180	1280092GT

- Fill out and sign the completion form included in this [safety notice](#) or attached to the installation instructions included in the kit and fax or email to Terex AWP Warranty Department. This will serve as verification that you have completed Safety Notice 170012.