

## **Safety Advisory - MSA Super-V Helmet Recall**

MSA recently determined that Super-V Protective Caps may not comply with the CSA (Canadian Standards Association) penetration performance requirement for a Type II (top and lateral) protective helmet if subjected to a lateral penetration in a room temperature or elevated temperature condition. This affects all Super-V caps manufactured before April 2017.

As a result of this condition, MSA is voluntarily recalling all Super-V helmets placed in service over the past five (5) years (April 2012 to April 2017). Super-V helmets placed in service before April 2012 (more than five (5) years ago) exceed MSA's recommended useful life, as stated in the user instructions, and should be discarded.

[Click here](#) to download recall information sheet